oy's Sad Death.

A 1 ng boy named Gilbert Halvey, aged

... la British army pensioner, Bengal merick, while climbing an e'econ the public road, in Mr Hurley's land .. Clino was electrocuted. Deceased came in contact with a high tebsion cable, and fell some 35 feet to the ground. When Edward O'Halloran, a plotholder, working nearby on Wednesday evening he saw the boy fall from the standard and went to his assistance. He saw that the boy's right hand was missing from the body, and was on the ground about a foot away. The boy was rushed to the County Infirmary where he died some hours later.

Thursday by Mr J S McNeice, Deputy City Coroner, Mr D J O'Mailey, solicitor, represented the E S.B.

At an inquest held at the Infirmary on

Edward O'Hanoran gave evidence on the lines mentioned above.

Patrick G Collier, District Engineer, E.S.B., gave evidence of visiting the ecens of the fatality at 9 30 pm, on Thursday evening. The standard was 42 leet high, with the wires 36 feet from the ground. Witness saw fresh clay marks on the standard, and there was a mark of burning on one wire as if it had been touched. There was a warning notice on the lattice steel mast standard eight feet from the groud.

The medical evidence showed that death

resulted from abook.

The jury returned a verdict accordingly, and recommended that the ES.B. should, if possible, do something to make the standards more difficult to climb.